

## ECS Configuration Change Request

Page 1 of 1 Pages

<b>CCR No.</b> 96-1436	<b>Logged Date</b> 12/19/96	<b>Rev.</b> -	<b>Request Type</b> CCR																		
<b>Priority</b> Routine <input type="checkbox"/> Urgent <input type="checkbox"/> Emergency <input checked="" type="checkbox"/>	<b>Affected Release</b>		<b>Change Class</b> II																		
<b>Title (description)</b> Transfer 8 monitors from EDF to EOC																					
<b>Documents Affected</b>		<b>Source Nos</b> (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference																			
<b>RTM Change</b> <input type="checkbox"/> <b>Start New Baseline</b> <input type="checkbox"/>																					
<b>Problem</b> The EOC needs eight monitors to display the spacecraft timing information. The monitors are currently located at the EDF and need to be shipped to the EOC at Goddard. The eight monitors requested for the move were purchased with systems which are currently being used as servers in the basement of the EDF which don't require monitors. EDS (Kareem Nakkash) has given permission to transfer them to the EOC.																					
<b>Proposed Solution</b> Transfer the following monitors to the EOC (coordinate with Rick Hudson for exact locations at the EOC): <table style="width: 100%; border-collapse: collapse;"><thead><tr><th>Part_ecn</th><th>Serial Number</th><th>Part_ecn</th><th>Serial Number</th><th>Part_ecn</th><th>Serial Number</th></tr></thead><tbody><tr><td>00000968</td><td>0010968-9527FC3390</td><td>00004577</td><td>0010968-6916GI0731</td><td>00004675</td><td>0010968-9621GI2930</td></tr><tr><td>00000919</td><td>0010968-9527FC540</td><td>00004680</td><td>0010968-9621GI2927</td><td>00000296</td><td>0010968-9438FC5692</td></tr></tbody></table>				Part_ecn	Serial Number	Part_ecn	Serial Number	Part_ecn	Serial Number	00000968	0010968-9527FC3390	00004577	0010968-6916GI0731	00004675	0010968-9621GI2930	00000919	0010968-9527FC540	00004680	0010968-9621GI2927	00000296	0010968-9438FC5692
Part_ecn	Serial Number	Part_ecn	Serial Number	Part_ecn	Serial Number																
00000968	0010968-9527FC3390	00004577	0010968-6916GI0731	00004675	0010968-9621GI2930																
00000919	0010968-9527FC540	00004680	0010968-9621GI2927	00000296	0010968-9438FC5692																
<b>Impact Analysis:</b> Organizations Affected: BOO <input type="checkbox"/> Contracts <input type="checkbox"/> ESO <input type="checkbox"/> FOS <input checked="" type="checkbox"/> M&O <input type="checkbox"/> QA <input type="checkbox"/> Rel. A <input type="checkbox"/> Rel. B <input type="checkbox"/> Rel. IR1 <input type="checkbox"/> MRS <input type="checkbox"/> SMO <input type="checkbox"/> Subconts <input type="checkbox"/> A.1 <input type="checkbox"/> Other _____ Cost: None <input checked="" type="checkbox"/> Small <input type="checkbox"/> Medium <input type="checkbox"/> Large <input type="checkbox"/> (Not exceeding \$100,000) (\$100,000 to \$500,000) (Over \$500,000) Schedule: None <input type="checkbox"/> Other January 15, 1997 Additional LOC _____ Man-Months _____ Materials _____																					
<b>Originator</b> <u>Marty Saletta</u> _____ Signature _____ Date _____																					
<b>Office</b> <u>FOS</u> <b>Office Manager</b> _____ Signature _____ Date _____																					
<b>Disposition</b> Approved <input type="checkbox"/> Approved w/Comment <input type="checkbox"/> Forward <input type="checkbox"/> Disapproved <input type="checkbox"/> <b>Comments:</b>          <b>CCB Chairperson</b> _____ Signature _____ Date _____																					